

## VME Intensity Monitor - Task #10380

Milestone # 9388 (New): 2015 Shutdown

### Implement a driver for the old vmeter-style digitizer at MI-30

10/02/2015 01:25 PM - John Diamond

<b>Status:</b>	Closed	<b>Start date:</b>	10/02/2015
<b>Priority:</b>	Urgent	<b>Due date:</b>	
<b>Assignee:</b>	John Diamond	<b>% Done:</b>	100%
<b>Category:</b>		<b>Estimated time:</b>	6.00 hours
<b>Target version:</b>		<b>Spent time:</b>	1.00 hour
<b>Description</b>			
The digitizer firmware version at MI-30 is being held-back. The register maps are completely different between the old and new styles. We'll need to fork the MI/RR Toroid digitizer driver and make a version that works with the old firmware.			

#### History

##### #1 - 10/02/2015 03:13 PM - John Diamond

- Status changed from New to Closed
- % Done changed from 0 to 100

Turns out we ported the Linac-style ADC driver for PXIE a few months back. Updated the mi30tor startup script to use that now.